



LEAN SIX SIGMA

K.M.Eazhil
Assistant Professor
Department of Mechanical Engineering
SNS College of Engineering
Coimbatore



Which of the p value indicates a stable data

- A. 0.67
- B. 0.03
- C. 0.019
- D. A&B

Which of these are not Multivariate analyses?

- A. Factor analysis
- B. MANOVA
- C. ANOVA
- D. Cluster analysis

Which of the following is a non parametric test

- A. Regression
- B. 2 tailed 2 sample t test
- C. ANOVA
- D. Kruksal test

It is a technique to trace the rule responsible for the problem and break the assumption for the process

- A. Assumption Busting
- B. Analogy Technique
- C. Benchmarking
- D. Constrained Brain writing